

***Downstream project Area - on high bank -  
view toward chute at right mid-ground.  
All ground level photos from March 2000.***





***In chute footprint, Lower outlet site -  
looking north,  
mud about 90-100 ft wide -***



***Lower outlet site - looking south -  
mud about 90-100 ft wide***








*Dike 695.1 (middle outlet) -  
Outlet channel would flow right to left along dike.*





*Dike 695.1 (middle outlet) -  
looking northwest, landward;  
outlet channel would flow where standing.*





*Dike 695.1 (middle outlet) - looking riverward; outlet channel would flow where standing, along dike. River bank is just beyond tall trees.*



***Broader view of Middle outlet area, viewed from north.***





***Chute area well  
upstream of dike 695.1  
looking southerly =  
100+ feet width water.***





***Upstream Outlet site, view toward riverbank past  
tall trees, along downstream side of dike 695.6.***





***Looking upstream from approx. dike 695.6, from high bank, view northeast up Channel B, with field road crossing at upper left - channel mud approx. 150-200 ft wide.***





***Disposal Area is field across middle of view.***






***Site of upstream inlet, looking toward river along  
Channel A alignment .***







*Site of upper inlet, view south.*




***Site of lower inlet, view toward  
river along Channel B alignment.***






**Aerial View after 1996 flood.  
Conditions have changed somewhat since photo.**





**View east-northeast, June 1996 after flood.  
Conditions have changed somewhat since photo.**





**View west, June 1996 after flood.  
Conditions have changed somewhat since photo.**

